



Service Center Metals Scrap Delivery Instructions

- 1 Enter Driveway at 6000 Quality Way
- 2 If the Truck Scale is Occupied, Wait Here
- 3 Weigh-In at Truck Scale, Stay in Your Truck on the Scale, Your Paperwork will be Brought to You, and You Will be Directed Where to Proceed Next
- 4 Flatbed Delivery Unloading Area (Inside Plant)
- 5 Van Delivery Unloading Area (Rear Dock)

Safety Requirements:

Stay Close to Your Truck ... Do Not Wander in Plant

Inside the Plant, You Must Wear a Hard Hat, Safety Glasses and Ear Plugs (Which SCM Will Provide if Necessary)

